NRAY Neutron Radiography Sample Image - Rubber and Hydrogenous Materials



The image above is a neutron radiograph of four air bag initiators. The second part from the left is missing an o-ring at the bottom and is therefore dysfunctional. Due to the ability of neutron radiography to image rubber and other hydrogenous materials so well, it is an effective complex component reliability testing technique